

# City of Port St. Lucie

121 SW Port St. Lucie Blvd. Port St. Lucie, Florida 34984

## Legislation Details (With Text)

File #: 2019-800 Version: 1 Name:

Type:OrdinanceStatus:PassedFile created:8/19/2019In control:City CouncilOn agenda:10/14/2019Final action:10/14/2019

Title: Ordinance 19-70, Approve an Ordinance Amending Section 64.09, Interceptors, of the City's Code of

Ordinances

Sponsors:

Indexes:

Code sections:

Attachments: 1. Ordinance Amending 64.09 Interceptors\_final 7.11.pdf

Date	Ver.	Action By	Action	Result
10/14/2019	1	City Council	Approved	Pass

Placement: First Reading of Ordinances

Action Requested: Motion / Vote

Ordinance 19-70, Approve an Ordinance Amending Section 64.09, Interceptors, of the City's Code of Ordinances

Submitted By: Donna Rhoden, Utility Systems Deputy Director

Strategic Plan Link: The City's Goal of high-quality infrastructure and facilities.

Executive Summary (General Business): It is essential that the introduction of fats, oils, and grease (FOG) into the City's wastewater collection system be limited so that FOG does not interfere with the operations of wastewater/sewer mains, lift stations, and treatment facilities. The existing language in Section 64.09 of the Code of Ordinances does not adequately address current industry standards for FOG interceptor operations, inspections or remedial actions customers must take to bring interceptors at their service locations into compliance.

Presentation Information: N/A

Staff Recommendation: Move that the Council adopt the attached ordinance

#### Alternate Recommendations:

1. Move that the Council amend the recommendation

2. Move that the Council provide staff direction

Background: During Fiscal Year 2017-18, the Utility Systems Dept. added a dedicated staff position for a Pretreatment Coordinator. It is that position's responsibility to inspect the more than 500 interceptors

## File #: 2019-800, Version: 1

associated with customer locations connected to the City's wastewater collection system that are typically used to reduce the amount of FOG from reaching the City's wastewater treatment plants. While performing inspections, the Coordinator noted several code violations primarily related to the customer's responsibility to maintain interceptors. Some customers have brought their interceptors into compliance and established regular pumping/maintenance routines, but others balked at the Utility's enforcement attempts. The attached ordinance reflects current utility industry standards; clarifies provisions regarding violations; defines the City's enforcement procedures and methods; and provides for variances.

Issues/Analysis: N/A

Financial Information: N/A

Special Consideration: N/A

Location of Project: N/A

Attachments: Ordinance

NOTE: All of the listed items in the "Attachment" section above are in the custody of the City Clerk. Any item(s) not provided in City Council packets are available upon request from the City Clerk.

## LEGAL SUFFICIENCY REVIEW:

Choose an item.