



Action Target Inc. 3411 S. Mountain Vista Parkway, Provo, UT 84606-0636 801-377-8033 FAX: 801-377-8096

Port St. Lucie Police Dept.

Quotation: 155358 By: Shannon Leetham Printed: 2026-May-28

Included Items:

- 4 **Year 2026 - Four, One Day Service Visits per year (8 hours maximum, no minimum) for an Annual Maintenance Agreement (4 visits within 12 months). No parts included unless specifically listed on the quote. This Agreement is for 4 visits per year for \$2150 per visit. We invoice the \$2150 after each visit is completed. Total for four visits is \$8600. 8,600.00**

If DCU filters are needed to be changed, that can be done at one of your regular maintenance visits. Tech will let you know at a visit prior if the filters will need to be changed on the next visit.

For details on what a quarterly range maintenance visit intel's, please read comments below.

- 8 **Year 2026 Monthly Range inspection and minor repairs as needed. 10,000.00**
- *Check Trap
 - *Check all back shells
 - *check barrel to see fill line and move barrels around
 - *look at electrical, wiring and make sure they turn and edge properly.
 - *Check DCU
 - *DRM Pro

6 **Year 2026 Hazardous Waste Disposal through RES** 15,000.00

A 2 cubic yard super sack on a pallet will be APPROX. \$2200 - \$2500 each. Subject to cost.

Service as needed. Depending on how many pallets are picked up, is to what the cost is above.

***Range Sweeps - Any contents from the HEPA Vac collected during long term cleanings, that includes higher accumulations of unspent gun powder. We do dispose of this, but it can not be put into the 'range fines' or the 'lead contaminated filters'. Special pricing and packaging is required if interested. ***

Pricing is based on approved waste: lead contaminated filters, ppe, and other lead contaminated debris produced by the range.

Pricing includes:

UN-rated packaging required by EPA/DOT

All documentation including Waste Profile and Manifest (Customer will receive the customer copy of the manifest on pickup. Customer will receive the facility signed off copy by mail within 35 days of proper disposal) Pickup at their facility Disposal at hazardous waste landfill

Environmental, insurance, and security fees

Fuel surcharge LTL Stop fee

6 **PN 38129 - DCU Filter, Camfil. This price is for filters only. Shipping cost will be added when time to ship.** 7,866.30

Purchase As Needed, Tech will let us know at visit when the filters will be needed.

Tech that changes out the filters on maintenance visit will only package up the filters if customer is on Action Target HazWaste program. Before visit, ATI will ship bags/pallets for the hazwaste to be packaged up and be ready for pickup.

Price subject to change. Quote for this price is good for 30 Days.

2 **Year 2026 - 2 Techs for 2 days to pull out full lead barrel bags and secure on pallets for shipment. Replace bags and hook barrels back up.** 7,300.00

This is as needed. When barrels are 75% full, we recommend them to have the bags pulled and staged for pickup. Tech will watch this as well, as Port St. Lucie. Barrels can be moved around to they fill at the same time.

Service as needed.

Replacement bags/Pallets are free as long as you are on our Metals Program.

Quote good for 30 Days.

- 4 **Year 2027 - Four, One Day Service Visits per year (8 hours maximum, no minimum) for an Annual Maintenance Agreement (4 visits within 12 months). No parts included unless specifically listed on the quote. This Agreement is for 4 visits per year for \$2200 per visit. We invoice the \$2200 after each visit is completed. Total for four visits is \$8800. 8,800.00**

If DCU filters are needed to be changed, that can be done at one of your regular maintenance visits. Tech will let you know at a visit prior if the filters will need to be changed on the next visit.

For details on what a quarterly range maintenance visit intel's, please read comments below.

- 12 **Year 2027 Monthly Range inspection and minor repairs as needed. 15,600.00**

- *Check Trap
- *Check all back shells
- *check barrel to see fill line and move barrels around
- *look at electrical, wiring and make sure they turn and edge properly.
- *Check DCU
- *DRM Pro

- 6 **Year 2027 Hazardous Waste Disposal through RES 15,000.00**

A 2 cubic yard super sack on a pallet will be APPROX. \$2200 - \$2500 each.
Subject to cost.

Service as needed. Depending on how many pallets are picked up, is to what the cost is above.

***Range Sweeps - Any contents from the HEPA Vac collected during long term cleanings, that includes higher accumulations of unspent gun powder. We do dispose of this, but it can not be put into the 'range fines' or the 'lead contaminated filters'. Special pricing and packaging is required if interested. ***

Pricing is based on approved waste: lead contaminated filters, ppe, and other lead contaminated debris produced by the range.

Pricing includes:

UN-rated packaging required by EPA/DOT

All documentation including Waste Profile and Manifest (Customer will receive the customer copy of the manifest on pickup. Customer will receive the facility signed off copy by mail within 35 days of proper disposal) Pickup at their facility Disposal at hazardous waste landfill

Environmental, insurance, and security fees

Fuel surcharge LTL Stop fee

- 6 **PN 38129 - DCU Filter, Camfil. This price is for filters only. Shipping cost will be added when time to ship.** 7,866.30
Purchase As Needed, Tech will let us know at visit when the filters will be needed.

Tech that changes out the filters on maintenance visit will only package up the filters if customer is on Action Target HazWaste program. Before visit, ATI will ship bags/pallets for the hazwaste to be packaged up and be ready for pickup.

Price subject to change. Quote for this price is good for 30 Days.

- 2 **Year 2027 - 2 Techs for 2 days to pull out full lead barrel bags and secure on pallets for shipment. Replace bags and hook barrels back up.** 7,400.00
This is as needed. When barrels are 75% full, we recommend them to have the bags pulled and staged for pickup. Tech will watch this as well, as Port St. Lucie. Barrels can be moved around to they fill at the same time.

Service as needed.

Replacement bags/Pallets are free as long as you are on our Metals Program.
Quote good for 30 Days.

- 1 **Metals Recycling - Agreement must be filled out and sent back.** 0.00
REcycling your metals with Action Target is easy and efficient. We will be there within 72 hours for the pickup. You will need to have the barrels strapped to the pallet and the lid on, ready for shipment.

Pick up as needed.

Total 103,432.60

Payment Terms:

Net 30

Shipping Terms:

NA

Installation Terms:

ATI Tech

Terms and Conditions:

You must reference the Order Number above on your purchase order to secure best price. Action Target reserves the right to adjust installation costs based upon the actual site conditions encountered. Unless explicitly itemized, price does not include taxes, bonds, fees, assessments, licenses, mandatory wage requirements or other regulatory costs which may be applicable to the job site.

Comments:

2 Year Contract for Quarterly Visits and Monthly Inspections- Four, One Day Service Visits over the course of 1 year, no parts included unless specifically noted on the quote. Work is for an 8 hour day maximum, no minimum. Price does not include parts.

8 Monthly visits the 1st year with minor repairs and inspection of range.

12 Monthly visits the 2nd year with minor repairs and inspection of range.

HazWaste, Metals Pick up, DCU Filters and Barrels emptied as Needed.

Lines 3,4,5,8,9 & 10 are all as needed.

Range Quarterly Maintenance Visit intel's:

Electric Target Systems

- *Turn on range computer(s) and launch control software.
- *Run targets to test functionality. Verify target speed and synchronization.
- *Edge and face targets 20 times.
- *Ensure all targets are in edge/face synchronization.
- *Ensure all targets are turning in the same direction.
- *Run several programmed scenarios to verify functionality.
- *Inspect actuators for damage. Paint with zinc paint where needed.
- *Inspect C-rods and repair or replace as needed. Tighten bolts connected to actuators
- *Inspect target clamps for functionality and damage. Align, tighten, repair, or replace as needed.
- *Inspect actuators, damage to control and/or power cables.
- *Inspect protective lumber and replace when needed.
- *Inspect connections on terminal strip at target and ensure proper voltage.
- *Inspect and secure electrical connections. Replace as needed.
- *Inspect all other hardware and tighten when needed.
- *Grease actuator bushings. Replace as needed.
- *Align and tighten target clamps.
- *Test and verify all target lighting functions.
- *Provide general inspection of all targets to diagnose any potential problems.

DRM Pro

- *Inspect track for damage and remove any debris.
- *Verify track is straight and level.
- *Verify track section junctions are aligned and smooth.
- *Verify track is solidly mounted to the concrete pad.
- *Inspect entire length of wire drive cable for kinks, unravelling, or other damage.
- *Verify spring tension is active.
- *Set cable tension to 50 lbs. at the trolley and verify performance. *Tension can then be adjusted to 40-60 lbs. to tune performance
- *Lubricate wire drive cable with dry lube PTFE spray. Do not use oil or grease. Spray dry lubricant directly on the cable.

- *Verify swivel upgrade has been installed.
- *Verify all power and control cables are in good shape.
- *Check system for missing or loose hardware, particularly in the motor end section. Motor bolts should be torqued to 33 ft. lbs.
- *Verify encoder pulley, encoder coupling, and encoder shaft all turn together with zero slipping between them. Note and correct any issues.
- *Verify motor and encoder pulleys do not wobble when they rotate. Note and correct any issues.
- *Inspect proximity sensors and sensor bracket for signs of damage or *being struck by a carrier.
- *Function test the runner end to end at least 20 times. Verify motion *start, motion stop, and correct distances.

TCT Bullet Trap

- *Inspect impact plates and joint strips for bowing or damage. Document bowing plates for flipping or replacement.
- *Inspect the S1 connection points for bowing, gaps, or escaping rounds. *Inspect areas behind the trap for damage or other evidence of escaping rounds. Clean and re-build S1 joints as needed.
- *Inspect chamber deflector edges for damage. Document damage for replacement.
- *Measure the middle of the mouth opening for each chamber to ensure a minimum of 1/2" opening. Note the chamber numbers and indicate if the trap is used primarily for pistol or rifle.
- *Use a scope camera to examine chamber interiors.
- *Inspect wall deflectors for gaps between the steel and the wall. Tighten as needed.
- *Inspect the backs of the declaration chambers for damage or wear.
- *Check shell cams are securely fastened and adjusted.
- *Inspect chambers for evidence of leaking and seal as needed.
- *Inspect lead evacuation ports for blockages or ingots. Clear and clean as needed.
- *Inspect gaskets and caulking to ensure tight seals.

Lead Barrels Emptied

- *As needed, visit will be needed to pull all the bags and get packed and ready for shipping. If on Metals Recycling program, barrels and pallets are free.

NOTE - Replacement of bullet trap components may require additional workdays beyond the pre-scheduled maintenance plan labor.

DCU Dust Collection Unit

- *Inspect duct work for clogs and damage. Empty and repair as needed.
- *Inspect the motor shaft. Grease/lube as needed.
- *Verify motors are rotating the correct direction.
- *Inspect flow gates under the trap, test air flow, and adjust to correct specifications as needed.
- *Test entire system for leaks. Repair as needed.
- *Check Photohelic set points and adjust static pressure controls as necessary. (low = .5 high = 3.5)
- *Verify and test purge cycle functionality.

- *Verify and test automatic breach detection system and horn.
- *Inspect DCU filters. Verify correct installation. Verify tight seals. *Replace filters as needed.
- *Check DCU filter door gasket.
- *Inspect DCU air compressor.
- *Verify correct pressure settings and adjust if necessary. (90-125 psi)
- *Check oil level and air filter. Replace as needed.
- *Inspect belts and hoses. Replace as needed.
- *Drain water condensation buildup.
- *DCU FILTERS can be changed out on a maintenance visit. Tech will inform on visit if they need to be changed out at next visit. Purchase as needed.

HazWaste Recycling

This is as needed. If signed up for hazwaste, bags and pallets are no charge.

***Range Sweeps - Any contents from the HEPA Vac collected during long term cleanings, that includes higher accumulations of unspent gun powder. We do dispose of this, but it can not be put into the 'range fines' or the 'lead contaminated filters'. Special pricing and packaging is required if interested.

Action Target is a sole source supplier for ATI INC. parts and service.

NOTES:

- * Parts are not included in the above rates unless specifically noted on the quote. 3 year Warranty parts are excluded due to having a warranty. Warranty parts are covered if they have a manufactures defect. Shot up parts, or damaged parts are not covered under warranty.
- * Rates include all labor, travel, lodging, and other expenses.
- * Extraordinary repairs or materials may require additional workdays billed above and beyond the scheduled maintenance days.
- * Range must be cleaned prior to the Tech's arrival for service.
- * Please email pictures of the range and equipment to sleetham@actiontarget.com prior to visit.

Terms and Conditions

Payment: All previous invoices must be paid in full prior to service. Payment for individual maintenance plan visits and resulting parts (if necessary) will be invoiced immediately following the visit. All payments are due within 30 days of receipt of invoice. Multiple visit maintenance plans allow for discounted prices on visits only, not parts. The discounted prices are based on how many visits will be made during the contract period which is typically one year. If you do not accept and schedule every visit in the contract, the discounted prices for the previous visits will be adjusted retroactively to reflect the actual number of visits and you will be invoiced accordingly. If your account is on credit hold. Action Target will not send a technician until the account is current.

Parts: Unless specifically included with this proposal, all parts used during maintenance visits are extra. Parts will not be used or ordered without approval from the facility personnel. ATI can utilize spare parts the

facility has on hand to accomplish minor repairs. Should an extra visit be required to install ordered parts, additional charges may be incurred. It is recommended that you secure a separate parts allowance during the maintenance approval process. This will allow you to order parts when needed without going through a separate approval process each time.

Scheduling: Please call or email me to request a visit date allowing for at least 6 weeks of lead time. Or scheduled all visits for the year in advance. A visit occurring with less lead time may incur additional expedited travel charges.

NOTE: If you cancel within 5 days of a scheduled visit, Action Target will bill you for \$500 to help cover the cost of canceled airfare and other expenses incurred. If you cancel in less than 2 days, this could be higher due to airfare cancelation fees and not being able to reschedule a visit for the Tech. The full amount of the visit maybe and can be charged.

Scope of Work: ATI will service ATI furnished devices/parts/systems only. Service on third party equipment or components may need to be referred to the original manufacturer. Maintenance visits are not renovations or remodels. ATI's work is limited to functionality testing, reasonable repairs, adjustments, safety check, and overall operational maintenance.

Unless specifically included in this proposal, heavy maintenance items like dropping auger troughs, flipping bullet trap plates, changing bullet trap chambers etc. are not included in normal maintenance visits. Heavy maintenance services are available and can be scheduled separately. This is not covered under warranty.

If access to the range is through any door narrower than 48", labor costs may be significantly impacted. Work areas must be clean and free from storage items, equipment, tools, or other obstacles that might impede access to work areas or limit ability to perform contracted work.

Labor and scope of work details are based on "one day" being defined as an 8-hour period. It is possible that the scope of work may be completed in less than 8 hours.

Lead Remediation: Unless specifically included in this proposal, ATI is not responsible for any removal of lead or cleaning the facility of lead. The facility is responsible for disposal and recycling of lead and other waste from housekeeping and maintenance services. The facility is also responsible for disposal of replaced equipment or components like impact plates, bullet trap chambers, etc.

Exclusions: ATI is not responsible for the following:

1. Any ATI system parts, devices, air compressors, or structures that are damaged due to accidents, normal wear and tear, abuse, negligence, acts of God, absence of recommended cleaning, lubrication, absence of recommended preventative maintenance, or ballistic damage due to inappropriate ballistic application or ammunition.
2. Prevailing wage, holiday pay, or premium time labor.
3. Any material or labor not included in the foregoing.
4. Any required line power, outlets, or power panels.

5. Permits, bonds, licenses, taxes, engineering, drawings, or reports not listed above.
6. Collection and removal of lead and/or lead dust or fragments.
7. Dumpster or other disposal or waste transportation costs.
8. Structural design.
9. Concrete including cutting, coring, and patching.
10. Site preparation. (Electrical outlets, buried utility lines or conduits, drainage, etc.)
11. Offloading or lift gate delivery.
12. Removal of walls or other construction elements.
13. Removal of dirt, rocks, or other debris blocking access to work areas or range equipment.

* Parts are not included in the above rates and will be billed separately as needed and approved. Parts not covered are parts damaged by customer. Warranty parts are manufactures defected parts.

* Rates include all labor, travel, lodging, PPE, insurance, and other expenses.

* See the following pages for a detailed description of services, terms, and conditions.

* Extraordinary repairs or materials may require additional workdays billed above and beyond the scheduled maintenance days.

Disclosure Statement: "Any and all information and data contained herein is the property of Action Target Inc (ATI); and shall not for any reason, whether tangible or intangible, be disclosed, duplicated, or used, in whole or in part, for any reason other than to evaluate this quote."

"Customer understands and acknowledges that ATI has expended and continues to expend significant time and expense in recruiting and training its employees, agents, representatives, and contractors ("Covered Person") and that the loss of any Covered Persons would cause significant and irreparable harm to ATI. Customer agrees and covenants not to solicit directly or indirectly, hire, or recruit, or attempt to solicit, hire, or recruit, any Covered Person or any Covered Person who has been employed by or hired by ATI in the previous 12 months or induce the termination of employment or contract of any Covered Person, regardless of the reason for the termination.

This non-solicitation provision explicitly covers all forms of oral, written, or electronic communication, including, but not limited to, communications by email, regular mail, express mail, telephone, fax, instant message, and social media, including, but not limited to, Facebook, LinkedIn, Instagram, and Twitter, and any other social media platform, whether or not in existence at the time of entering into this Agreement."

Email, Fax or mail this signed proposal to begin scheduling your maintenance visits.

Fax Number
801-377-8096

Mail Address

Action Target / ATTN: Maintenance Plans / 3411 S. Mountain Vista Parkway / Provo, UT / 84606

Or Contact Shannon Leetham 801-705-9170 Sleetham@actiontarget.com with additional questions or for more information.

Maintenance Plan Approval Signature: _____

Printed Name: _____

Approval Date: _____